


PRS Hollowbody Electronics Diagram

Pre-2007



Current

Note: Shielded Jack Cable is soldered to ground of 3-way toggle. Shielded cables of pickup harness wires are soldered to jack cable. Black ground wire is soldered to shielding of pickup harness. Solder bridge ground wire to any shielded cable of pickup harness.

